

Using the Courier V32 modem for BACS

We have recently investigated a new version of the Courier V32 modem for BACS communication. This modem required different programming options to be set when used at the end user site, although the previously recommended parameters worked OK at our London offices (see technical bulletin GT641, 24 NOVEMBER 1993). We suggest you now try the programming command:-

```
AT&M1S13=8&S1&X0
```

and if this does not work try:-

```
AT&M1S13=8&S1&X2
```

The phone number and configuration commands are as per technical bulletin GT641.

Important Note: Resellers who are attempting to use V.32 synchronous Comms to interface to BACS should be aware that the telephone numbers for V.32 synchronous connections are different from the numbers used for V.26 synchronous Comms. Please contact your BACS representative for further details.